

Property	Test Method	Unit	Value
Specific gravity @25/25 C	D-70	DC	1.01-1.05
Penetration @25 C	D-5	DC	85/100
Softening point C	D-36	DC	45/52
Ductility @25 C	D-113	DC	MIN 100
Loss on heating	D-6	WT%	MAX 0.5
Drop in penetration after heating	D-6 & D-5	%	MAX 20
Flash point C	D-92	DC	MAX 232
Solubility in CS2	D-4	WT%	MIN 99.5
Organic matter insoluble in CS2	D-4	WT%	MAX 0.2
Spot test	A.A.S.H.O.T.102		negative
Flash Point C	D-92	DC	MIN 232