

Property	Test Method	Unit	Value
Specific gravity @25/25 C	D-70	DC	1.01-1.06
Penetration @25 C	D-5	DC	60/70
Softening point C	D-36	DC	49/56
Ductility @25 C	D-113	DC	MIN 100
Loss on heating	D-6	WT%	MAX 0.2
Drop in penetration after heating	D-6 & D-5	%	MAX 20
Flash point C	D-92	DC	MIN 250
Solubility in CS2	D-4	WT%	99.5 min
Spot test	A.A.S.H.O.T.102		negative